



PO Box 837 Quitman Ga 31643

Oil comparison test

Equipment:

Sumitomo SM Cyclo HH3245 reducer 30 hp, driving 320' inclined OSB flight conveyor

Week one

Thursday am

Drained and replaced Exxon EP 150

Friday am

No load condition read 38 amps

Week two

Thursday am

Drained and replaced with Primrose 514-M

Friday am

No load condition read 28 amps

We checked reducer temperature both weeks. Ambient had about 40 degrees spread. Best guess, reducer is running about 15 degrees cooler with 514-M.

A handwritten signature in black ink, appearing to read "Shawn O'Connor". The signature is fluid and cursive, with a large initial "S" and "O".

Shawn O'Connor
Mechanical Superintendent
Langboard Inc. OSB